59-0088

05 Oct 72

87th FIS

	II in all spaces	~~~		RIEL INVOLVEE (A		FOR GROUND	ACCIDENTS (NLY
5 Octo Thursd	her 1972	1		106A 59-088	pplicable)	Base Code •	ond Report Sei	rúst 71. :
5 Stat 2820/5	ecummence: state, come base, upentify. If ute miles sout ONM from K. I.	off BASE GIVE th of Watto Sawyer Af	oistance on, Mic B. Mic	raom mearest base higan higan	1530 ES	AL .	DAY [
MAJOR COMMA	TION POSSESSING/DWI	ří.	S 1 0 H	EL AT TIME OF MI WING 	GROUP	SQUADRON OF 87 FI	S HAME A	Sa
ð				chicle, if they	differ from Ites	7 above)		
	Division (ADC	Duluth	Intern			ota.		
LAST NAME	. FIRST NAME, MIDO	See AFM 127-2		127-4 for specif	In Instructions ASSIGNED	AERD"	I IMPUNI	DĄY
Ankley	Donald	с.	Maj		FP	SR Pil	Lot TT	ON
						<u> </u>		
								-34
	NO. 11 No. 11 April 25 / 40 .						-	
		Sileonelleza						
7 (7 (8 (1 (1)))	icable letter(%) i Foral-PT; Fatal-F; DESCRIPTION OF ACCID	winning- Mr)						fanci
lemfing to findings, a Attache	the mishep, the rea and recommunications, ad Story of Fligh	and any correct	gation and Live activ	fanalysje to locf on taken.	ude discussion of	nil cause f	actors lister	1.
a, Bis	or The Land							· · · .
a, Bis								
a, Bi;								
a, Bi;						and the second of the second o		
a, Hi;								
a, Hi;						in the second of		

AF JAN 70 711

PREVIOUS COTTION OF THIS THRM IS ORROLETE.

A-1441.h

Paragraph 11a, AF Form 711

HISTORY OF FLIGHT

On the afternoon of 5 October 1972 5 F-106 aircraft of the 87th Fighter Interceptor Squadron participated in a practice flush exercise initiated by the unit. All pilots attended the morning commander's briefing at 0730L followed immediately by All pilots attended the the mission briefing. The briefing was conducted by the squad-ron Flight Examiner and covered all items in the ADCM 51-106 briefing guide. The emergency procedures for the day was engine flameout and airstart. The mission, a practice flush with normal radar intercept training under GCI control, was scheduled for 0900L but was delayed due to poor weather conditions. The weather improved to the extent that a mission rebrief was held at 1410L with takeoff planned for 1500L.

Major Donald C. Ankley was assigned aircraft #59-088. He completed the normal preflight then waited in the cockpit for the flush signal. Major Ankley attempted two combustion starts prior to a successful pneumatic start. Normal taxi and end of runway checks were accomplished and Major Ankley's was the second aircraft airborne at 1515L. The weather at takeoff was partial obscuration estimated 1000 ft overcast and 5 miles in fog with a calm condition. Takeoff and climb to assigned flush altitude of 16,000 ft was normal. Climb and level off checks were completed with no abnormal instrument indications.

At approximately 1527L Major Ankley, concentrating on the radar scope, saw the scope go blank and felt a decrease in thrust sufficient to push him forward toward the scope. Ma jor Ankley looked at the warning panel and saw the AC & DO fail lites, both boost pump fail lites and the oil pressure lite illuminated. The RPM was decaying through 60% with decreasing The fuel flow and oil pressure gages both read zero. A quick airstart was attempted on the normal fuel system with no response on any gages. At this point a MAY DAY call was made but there was no UHF side tone, indicative of a doubtful tradamission. Major Ankley then selected omergency on the IFF'SIF equipment and simultaneously realized the flight controls had frozon. A cloud layer was also enter/id at this time A cloud layer was also enterfid at this time. The airspood had decayed from a craise appeal of 310KIAS to 250kIAS. The RAT (Ram Air Turbine) was deployed and flight control response was regained. Air speed was maintained at 250KIAS.

With the aircraft under control and once again in VFR conditions, Major Ankley attempted two more airstarts, the last being the ground start procedure. Again there was no response on any of the gages nor any noise to indicate an airstart. Major Ankley saw 10,000 it on the altimeter at this time and concentrated his efforts on locating a suitable bailout area. Weather in the area was estimated to be 3,000 ft scattered, 15,000 ft overcast and 3 to 5 miles in haze.

Bailout was initiated at 5,000 ft and 220KIAS. had positioned the aircraft on a southerly heading over open country just south of several farms and pointed toward a wooded ared. The aircraft impacted at approximately 1530L in a heavily wooded swamp area. The aircraft exploded scattering debris in The aircraft exploded scattering debris in excess of 700 ft from the initial impact point. Major Ankley landed in a rocky field three quarters of a mile from the air-

(This is a privileged do ment a releasable in whole or in part to persons or agence outside the Air Force without the express approval of the secretary of the Air Force).

FOR OFFICIAL USE ONLY

craft impact and suffered a fracture of the left ankle. Several local farmers are ved almost immediately to assist the downed pilot.

Major Ankley used his survival radio to vector two other F-106 aircraft to his location. They spotted the chute and wreckage noting both positions for future references. Major Ankley was picked up by a local ambulance and driven to the K. I. Sawyer AFB hospital.

FOR OFFICIAL USE ONLY

(This is a privileged doom in not releasable in whole or in part to persons or age discloutside the Air Force without the express approval of the Secretary of the Air Force).